

2141 ICON Way, Vacaville, CA 95688 - Tel: 707.564.4000 - www.iconaircraft.com

NOTIFICATION

N-021016 REV A

DATE ISSUED: 02/10/16
DATE EFFECTIVE: 02/10/16
SUPERSEDES NOTICE: None

SUBJECT: Oil Tank Bracket
AIRCRAFT AFFECTED: MODEL: A5

S/N: 00001, 00002, 00003

REQUIRED ACTION: Inspect Oil Tank Bracket for Cracking

TIME OF COMPLIANCE: Initial Inspection before next flight and every 20 hours of flight after.

PURPOSE: ICON Aircraft has found during a ground inspection that the oil tank bracket was fractured which could result in the oil tank coming lose. The purpose of this notification is to provide instructions to inspect the oil tank bracket to check for cracks.

ICON Aircraft, Inc. is continuing to investigate the cause of the fractures. Once determined, ICON will communicate the resolution and provide any additional instructions or replacement parts as deemed necessary.

PARTS LIST:

PART	DESCRIPTION	A5

INSTRUCTIONS:

- 1. After each flight, locate oil tank per Maintenance Manual Chapter 3.6.2, and inspect the oil tank bracket for cracks.
- 2. If no cracks are observed, reinstall engine cowling per Maintenance Manual Chapter 3.4.2, and repeat inspection every 20 flight hours.
- 3. If cracks are found please contact ICON Aircraft, Owners Center prior to continuing flight operations.

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and notify ICON Aircraft, Owners Center at:

ICON Aircraft
2141 ICON Way
Vacaville, CA 95688
(855) FLY-ICON or (707) 564-4000
support@iconaircraft.com

Please include the aircraft registration number, serial number, your name, and if known the contact information of the new owner/operator.

ICA009717-B PAGE 1 of 2



2141 ICON Way, Vacaville, CA 95688 - Tel: 707.564.4000 - <u>www.iconaircraft.com</u>

NOTIFICATION

N-021016 REV A

ICA009717-B PAGE 2 of 2