

2141 ICON Way, Vacaville, CA 95688 - Tel: 707.564.4000 - www.iconaircraft.com

SAFETY DIRECTIVE/ALERT

SD-061417 REV B

DATE ISSUED: 06/15/2017 **DATE EFFECTIVE:** 06/15/2017

SUPERSEDES NOTICE: SD-051117-B SD-051117-A, SD-061417-A

SUBJECT: Throttle cable assembly damage

AIRCRAFT AFFECTED: MODEL: A5

S/N: 00001,00003-00020

REQUIRED ACTION: Discontinue flight of the aircraft

TIME OF COMPLIANCE: 1) Immediately

PURPOSE:

ICON is committed to designing, manufacturing, delivering, and supporting a high quality Light Sport Aircraft, providing a level of safety well beyond expectations. ICON has experienced reports of throttle assembly damage. At this time ICON is investigating the root cause of the damage. Until that investigation is complete and a corrective action is identified and implemented, all affected aircraft shall discontinue flight immediately.

PARTS LIST:

N/A

Notification and Action:

The logbook entry is not required. Acknowledge and notify ICON Aircraft Customer Service and Support of the Safety Directive SD-061417 has been complied with required action.

If you need assistance relocating your A5 to your home base or temporary storage arrangements, please contact ICON Aircraft and ask for Customer Service and Support.

If you are no longer owner/operator of this aircraft, please forward this information to the present owner/operator and notify ICON Aircraft, Owners Center at:

ICON Aircraft
2141 ICON Way
Vacaville, CA 95688
(855) FLY-ICON or (707) 564-4000

support@iconaircraft.com

Please include the aircraft registration number, serial number, your name, and if known the contact information of the new owner/operator.

ICA009719-B PAGE 1 of 2

SAFETY DIRECTIVE APPROVAL

Bret Davenport		
	Compliance/CS&S Engineering	6/15/2017
NAME	TITLE	DATE
NAME	TITLE	DATE
NAME	TITLE	DATE
NAME	TITLE	DATE
	150	
	0	
· oc		
130.		

ICA009719-B PAGE 2 of 2