



2141 ICON Way, Suite 100, Vacaville, CA 95688 - Tel: 707.564.4000 – www.iconaircraft.com

SERVICE LETTER

SL-010424-A

- A5, Publication ICA015726 in back of the POH, to the new POH.
- b. Remove any pages associated with the MRA01059-POH-A supplement.
 2. Transcribe the Airplane Registration Number and Airplane Serial Number to the new Cover Page exactly as they appear on the current one.
 3. Ensure that all data in the Weight and Balance Record is transferred to the new POH. Failure to transfer this information could lead to compliance issues and the inability to properly maintain the airworthiness of the aircraft.
 4. Review the Record of Revisions and/or any revisions added by hand due to an MRA. Transfer any applicable revisions to the new POH. Contact ICON with any questions.
 5. Verify that all POH Chapters have a Change ID in the footer that matches the List of Effective Chapters.
 6. Sign (or initial) next to the 'Added By' column cell corresponding to this Handbook Revision at the top of the Record of Manual/Handbook Revisions.
 7. Discard all of the old pages removed from the handbook during the update process.
 8. Take some time to review and familiarize yourself with the content of each changed Chapter.

If applicable, make the following logbook entry:

“The instructions of Service Letter (SL-010424-A) have been complied with (ref. FAA Exemption 10829C)”.

If you have questions, comments, or concerns about this Service Letter and/or if you are no longer owner/operator of this aircraft, please forward this information to the present owner/operator and notify ICON Aircraft at:

ICON Aircraft
2141 ICON Way Suite 100,
Vacaville, CA 95688
(707) 564-4000

support@iconaircraft.com

Please include the aircraft registration number, serial number, your name, and if known the contact information of the new owner/operator.